## Aircraft Associates Notable Aircraft Maintenance History 11/6/23

<b>Registration</b> N777TK (N60311, N547G, N870GH)	<b>Make</b> Beechcraft	Model 1979 Beechcraft 58 Baron Foxstar			
Serial No.	Engine	Paint	Interior	MGTOW	EW
TH-1018	IO-550-C3F	Matterhorn White with Toreador Red and Black Velvet Accents (2015)	Cloud Gray with Castle Tan and Black Accents		
<b>Log</b> Airframe Log 1		Item(s) Addressed STANDARD airworthiness certificate issued Installed airborne pneumatic surface deice system kit no. 707B s/n 0793 IAW STC SA863CE Replaced RH prop control cable Replaced LH elevator outboard attach bracket and attach	Critical Item Boots installed		
	January-80 December-80 January-84	bracket screws Replaced RH throttle and mixture cable Overhauled Janitrol heater and installed hour meter for heater Removed and replaced elevator hinge assembly			
		Installed zero time overhauled exchange Janitrol heater Replaced surface deicer boots on tail Removed controls, stripped controls and aircraft. Repainted			
	December-85	controls and aircraft, checked control balance and reinstalled. Base in Sterling Matterhorn White, Sterling Light Blue and Imron Dark Blue.			
	January-88	Replaced windshield with factory new, repainted frame to i match aircraft. Aircraft weighed for c/w FAR 135 operation I Interior was repaired and inspected Removd LH rear fuel cell and installed new fuel cell			
	August-89	Installed Beech Kit 36-5013 to comply with SB No. 2045 Rev. 3 with fuel filler and caps Installed rebuilt fuel cell in RH wing leading edge			
Airframe Log 2	February-00	Replaced RH boost pump with new Replaced LH outboard leading edge fuel cell with new CW AD 91-15-20 engine mount modification per Beech MSB			
	March-00	23262 R1, by installing kit 58-9007-1-S and reinforcements Aircraft modified to Colemill Enterprises Inc. "Foxstar."			
		Installed TCM IO-S50C engines and Hartzell 4 bladed propellers HC-C4YF-2E/FC7063Q. Installed IAW STC SA1762SO Replaced cabin heater and pressure switch Replaced RH outboard leading edge fuel cell. Replaced nose wheel steering idler arm. Sent RH exhaust stack for repair by			
		<ul> <li>Aerospace Welding.</li> <li>Replaced left and right elevator assemblies due to corrosion</li> <li>with overhauled assemblies from Biggs Aircraft.</li> </ul>			
		Removed existing equipment and installed Garmin GNS 430 and GA56 antenna, Heads Up Technologies XMD076-01 XM weather satellite receiver, and a Comant Cl 420-1 XM Wx satellite antenna, GMA 340 audio panel, Garmin SL30 navcomm, Mid-Continent MD200-306 VOR/ILS, and a Sandia ACF 328 Avionics. Reinstalled one PWC-150 converter with a			
	March-06	12VDC power receptacle.			
		Installed and rigged new throttle and prop control cables. Installed new outboard gear door forward rod ends. New left and right main gear ice boot kit. Reinstalled landing box and gear motor after overhaul. Installed OH'd right inboard fuel cell. Stripped, cleaned and patched all cuts and resealed pneumatic ice boots. Installed new LH and RH wing root seals.			
		Removed small areas of minor surface corrosion. Installed PM research radome boot. Replaced deteriorated SCAT ducts. Repaired cabind door inner frame, cracked at lower hinge point. Installed .090 aluminum external and internal doubler, sealed with PRC1422 between skin and doubler and painted to			
		<ul> <li>match. Repaired INOP gear warning horn.</li> <li>Determined LH and RH alternator out sensors are defective but</li> <li>not corrected at owners request.</li> </ul>			
		Installed WAT LED Anti-collision light assembly on the vertical stabilizer tip. Installed OH'd left alternator. Installed new right alternator inoperative switch. Cleaned and waxed all deice			
	October-06 November-06	i boots. i Installed OH'd strobe power supply Repaired crack on right nacelle air induction air scoop. Installed repaired Lamar voltage regulator in place of existing. Installed FAA/PMA Left and Right Horizontal stabilizer deice boot and			
	September-07	<ul> <li>Vertical stabilizer deice boot.</li> <li>Upgraded GPS to WAAS with GA 35 antenna.</li> <li>Replaced XM data receiver with new part</li> </ul>			

	Replaced existing ELT with new ACK E-01 ELT unit. Repaired crack in tail light lens. Removed and replaced LH and RH aileron push/pull rods and rod ends with new. Fabricated new 1/4" think plywood floor panel aft of main spar. R&R'd forward retract rod end. Installed new Lord shimmy damper. Cleaned and treated outboard section of rod for corrosion on RH MLG outboad end. Installed new D'Shannon windshield. Removed prop feathering accumulators and all associated hoses, lines	
March-08	and hardwares.	
4	Reattached LH wing deice boot stall strip and repaired hole in boot. Installed corrected seat stops on RH aft facing seat. Replaced LH and RH flap bumpers with new. Installed new fuel placards. Removed and replaced RH tail pipe with OH'd tail pipe and rear exhaust hangers with new. Removed and	
	reinstalled repaired H engine crossover and vent tubes.	
August-09	Replaced circuit brakers to CW AD 2008-13-17	
December-09	Replaced deice system pressure relief valve with OH'd unit. Serviced windshield and prop anti-ice system with 10 quarts alcohol. Installed OH'd RH vacuum pump.	
	Replaced fuel line at LH wing tip fuel vent. Replaced pneumatic	
August-11	line in fuselage.	
	Removed all aircraft deice boots. Cleaned, prepped and installed new SMR Deice Boots. Replaced 2 solenoid valves with serviceable units. Installed OH'd exchange deice valve.	
December-11	Ops checked boots good.	New Boots
	Replaced RH prop deice boot with new.	
	Removed RH aft fuel cell and replaced with new fuel cell.	
January-14	Replaced RH electric boost pump with OH exchange.	
	Replaced LH engine intake air duct with new SCAT 12 hose	
0000001-14	Replaced Ell'engine intake an duct with new SCAT 12 hose	
	Complete chemical strip, etch, alodine or magnacoat as required with epoxy prime of the aircraft. Applied a base of Alumigrip Matterhorn White (AHS-1619) with AcryGlo Black Velvet and Toreador Red accents. Painted the registration numbers N870GH to meet FAR requirements using Acryglo Black Velvet 10684 and AcryGlo Toreador Red W00152 drop shadows. Applied temporary registration of N547G over the painted numbers. Applied basic placards. Installed new AeroSonix Radome Boot on nose radome. Installed new stainless hardware on aircraft exterior panels. Installed refurbished pitot tube. Repained dual yoke control gloss black.	
	Removed existing executive table and installed serviceable	
March-15	table. Installed new cockpit side windows and cabin windows IAW Great Lakes Aero Products STC SA0690CH.	New Paint, Windows, Table, Y
November-15	Replaced LH engine air pump with OH'd unit from Aero Accessories	
	Installed blind encoder on Transponder system to replace	
June-15	previous	
	Removed KCS 55A compass system, encoding altimeter, VSI, attitude gyro, turn coordinator, DME, GPS remote annunciator, inverter for MFD synchro, and pilot's floating instrument panel. Installed new custom floating panel and the following: Garming GS00 PFD/MFD system, OH'd standby attitude gyro, airspeed indicator, autopilot annunciator. Relocated #2 Nav indicator to lower subpanel and installed OH'd standby altimeter. Relocated the suction gauge to the RH side instrument panel. Reconfigured the EX-500 MFD to getting heading info from G500 system. Installed GAD 43e analog interface adapter. Certified new system altimeter and Garmin GTX 327 transponder. Installed cosmetic overlay panels on lower subpanel and right side instrument panel. Repaired KC-295 flight computer at Mid Continent. Removed and replaced KS-270 Pitch Servo with OH'd exchange unit.	New avionics
	Removed RH flap due to cracked nose rip at actuator and	
	repaired by SRS aviation and reinstalled and verified flap rigging. Replacd 2 pulleys aft of rear spar, 2 pulleys under rear cargo floor and 1 pulley aft of rear bulkhead. Replaced all wing bolts and nuts using wet method. Cleaned and treated minor corrosion where heat duct attaches to rear spar. Replaced oil drain patch plates on both lower cowls. Installed new ventral	
September-16	fin fairing. Bob Ripley	
	Installed new G&D Aero Products Acrylic Window Liners.	
October-16	Installed new prop deice boot on 1 RH propeller blade.	
November-16	Replaced LH alternator with OH'd Teledyne alternator.	
	Replaced RH engine instrument air pump with OH'd unit.	
December-16	Replaced heater combustion fan motor with OH'd unit	
	Installed OH'd alternator drive coupling assembly on OH'd	
December-16		
	Removed Garming GTX 327 and installed GTX 345. Removed	
	XM receiver and installed Garmin GDL69A. Removed and replaced LH engine ignition barness with new Renaired LH	

чернасеа LH engine ignition harness with new. Repaired LH July-17 engine inboard exhaust system at Dawley Aviation.

Yoke paint, SS Hardware

## Airframe Log 3

	Removed LH and RH props and governors and sent to Maxwell	
	Propeller for overhaul. Reinstalled in original positions after	
	overhaul. Sent both spinners to K&K Precision Welding for	
	repair. Replaced 8030 ASI with OH'd airspeed indicator unit.	
	Removed yoke assembly and landing light bezels, painted and	
	reinstalled. Installed new engine mounts on both engines.	
	Installed new gear warning horn switch. Rebuilt fwd, OB,	
	lower baffle on LH engine using new assemblies. Repaired OB	
	inter-cylinder baffles and Aux terminal wiring on RH engine	
Ostahan 1	and alternator. Installed new NLG door actuator shaft	
October-1	7 assembly.	
	Replaced alternate air duct on both engines with new SCAT tubing and LH alternator sensor. RH/IB fuel bladder repaired at	
Sentember-1	Bagle and reinstalled.	
September 1	Installed OH'd RH/OB fuel sending unit and OH'd LH fuel	
December-1		
	Removed OH'd engine starter and installed OH'd starter on #1	
November-1	-	
	CW AD 2004-21-05 Pressure Decay Test, now due 2/1/22. ELT	
	Battery expires 12/2023. Removed engines for OH. Installed	
	OH'd IO-550-BCC engine in LH position and OH'd IO-550-C	
	engine in RH position. New D'Shannon Aviation Baffle Kit	
	installed IAW STC SA09220SC and D'Shannon High	
	Performance Exhaust installed. New mixture control knobs,	
	EGT probe on RH exhaust, and repaired wiring on LH tach	
	generator installed. All flammable fluid lines in engine	
-	) compartments OH'd and installed.	New engines
	L Annual Inspection at Finefield Aviation	
June-2	L Replaced RH engine right side exhaust support clamp	
	Performed repair of RH engine air intake scoop by removing	
April 2	upper plate attach structure and fabricating replacement. L Performed repair of fiberglass where rivets pulled through.	
April-2.		
October-2	Replaced STBY attitude indicator with similar part with 3" light L tray and new hose.	
	Replaced KS 270 Pitch Servo with OH'd unit for KFC 200 Flight	
December-2	L Control System	
	Engine s/n 281993-R IO-550-BCC installed in LH position on	
LH Engine Log January-20		
	Replaced manifold pressure and alcohol deice hose assemblies	
	with original hose fittings and reinstalled. Pressure lubed	
	engine controls. Replaced mixture, throttle and prop control	
January-2	L rod ends and rigged. Replaced alternate air duct.	
	Engine s/n 810484-R IO-550-C installed in RH position on	
RH Engine Log January-20		
	Replaced manifold pressure and alcohol deice hose assemblies with original hose fittings and reinstalled. Pressure lubed	
	with original hose fittings and reinstalled. Pressure lubed engine controls. Replaced mixture and prop control rod ends	
lanuary-2	L and rigged. Replaced alternate air duct.	
Sandary 2.	Installed OH'd propeller after OH at Maxwell and spinner repair	
LH Propeller Log October-1	7 at K&K Precision welding.	
	Installed OH'd propeller after OH at Maxwell and spinner repair	
RH Propeller Log October-1	7 at K&K Precision welding.	