AIRCRAFT MAINTENANCE RECORDS

N 7883L

AVIONICS

LOG BOOK



AIRCRAFT MAINTENANCE RECORDS

Owner	
Aircraft Registration	N_7883L
Manufacturer	
Model	
Serial No.	
Position	

AIRCRAFT MAINTENANCE RECORD

Date Total Time

DESCRIPTION OF WORK PERFORMED
SIGNATURE & CERTIFICATE NUMBER OF PERSON PERFORMING WORK



The enclosed tailBeacon-TSO has been updated to the most recent ADS-B Firmware (Version 1.4.0). This complies with Service Bulletin UAV-1003174-001 Rev A and may be noted in the installation aircraft logbook.



Model:tailBeacon TSO P/N: UAV-1002183-001

UAVIONIK P/N: UAV-1002183-001 MOD: 0 S/N:2000194



SSID: Beacon-E928 Pass: FlightHeat

Certificate of Conformance

I hereby certify that the product/s enclosed herewith, manufactured by uAvionix Corporation, have been inspected and found to be in full accordance with the specifications of:

TSO-C154c B1S, TSO-C145e Beta 1 INCOMP, TSO-C88b,

and TSO-C30c Type III.

By:_____Country of Origin: U.S.A.

Date: 7-3-19 UAV-1003043-001 (Rev A



Model: tailBeacon TSO Installation Kit P/N: UAV-1003202-001

Certificate of Conformance

I hereby certify that the product/s enclosed herewith, manufactured by uAvionix Corporation, have been inspected and found to be in full accordance with the specifications of:

TSO-C30c INCOMP

By: ______COUNTRY of Origin: U.S.A.

Date: 47/1-19 UAV-1003264-001 (Rev A)



HIGH DESERT AVIATION, LLC 4025 SW AVIATION BLVD, PRINEVILLE, OR 97754 541-447-1822

hdaviation7@gmail.com

DATE: 05/13/2021

AIRCRAFT: N7883L BONANZA V35, S/N D-8301; TACH: 3904.62

C/W UAVIONIX SB 1.5.1 TAILBEACON FIDMWARE UPGRADE

ERIK COOK 3023411AP

SUB-TOTAL THIS PAGE

Look

TOTAL - CARRY FORWARD TO NEXT PAGE

AIRCRAFT MAINTENANCE RECORD Page No.

Date	Total Time		ESCRIPTION OF VERTIFICATE NUMBER		PERFORMING WORK	
acific Coast Avionics					CRS OPXR455L	
Registration: N7883L	Make: Beech	Model: V35	S/N: D-8301	Aircraft Time:		
temoved failed KT76A tran	sponder s/n 77956 and repl	aced with serviceable KT76A trans	sponder s/n 71904Performed 1	14 CFR 91.413(a) certifica	tion of the BendixKing KT 76A	
ransponder s/n 71904 and	found the transponder to r	neet the requirements of 14 CFR	Part 43 Appendix F.			
his aircraft has been inspe	cted in accordance with cur	rent federal aviation regulations a	and found to be alrworthy with	respect to the work perfe	ormed. Details will be on file at	
acific Coast Avionics unde	r Dennis Hedden, work orde	21-6086.		. 1		
	ROX	5		3C1P61	21	
Signatur	e: Terry Blaisdell	V- C-	D	ate: 6/29/2021		
org/return		Page	1 of 1			
		Traffic Linds Little			And the second second	
		H- In-				
ALL LANDS			Bull Salat Salat	- 15 5 1 100 11		
					A THE PROPERTY OF	
	THE RESIDENCE OF					
					The local Part of the last	
Election 21		11-13-14 3-44				
	The state of the s					
	SUB-TOTAL THIS PAGE					
		SUB-TOTAL THIS I	PAGE			