

AIRCRAFT LOG #1



PIPER

book is a

Instructions for the Use of Log Book

1. This log must always accompany the aircraft to which it refers.
2. No pages shall be torn from Log Book. No erasures, and all entries to be made in ink.
3. Original entries shall be made and signed by manufacturer or seller. All other entries shall be made by Pilot, Chief Mechanic, or other competent person authorized to do so.
4. On journey, the pilot is responsible for carriage of Log Book and entries or omissions therein. Failure to do so will be considered a serious neglect of duty.
5. Before departure on journey, pilot is personally to ascertain that entries in log have been made are correct, and then sign certificate to the effect.
6. Special data such as manufacturers notes, test data, reconditioning, etc., should be affixed to stubs provided for that purpose in the back of this book.
7. CAA-18-1 Repair and Alteration forms listed on last page.
8. This log book shall be available and produced, on demand of anyone so authorized.

PIPER AIRCRAFT CORP.—LOCK HAVEN, PA., U. S. A.

AIRCRAFT LOG

Aircraft Name *Piper* Model *PA 32 "160"* Serial No. *32-6207*
 Engine Name *Lycoming* Model *D-320-B2A* Serial No. *L-645-39*
 Description of Aircraft T.C. No. *1A6*
High wing land Cabin Monoplane
 Date of Manufacture

 Seating Capacity (including pilot) *4* Wt. Empty *1137* Gross Wt. *2000*
 Make of Propeller *Sensenich* Hub Design No. Hub Serial
 Blade Design No. *M74DM* Blade Serial Nos. *26943*
 Owner
 Address
 Transferred to Date

NOTICE:—Making false entries in this book is a violation of the Civil Aeronautics Act of 1938, punishable by Civil Penalty.

Total Forward

Date of Last Overhaul

NOTICE:—Making false entries in this book is a violation of the Civil Aeronautics Act of 1938, punishable by Civil Penalty.

AIRCRAFT LOG

REMARKS

SIGNATURE

I have inspected this aircraft and found it complies with the requirements of CAR 1.67. Certificate of Airworthiness dated6-27-58..... was issued by me.

James. M. M. M. M.

J. W. McNary
Asst. Chief Engineer
Piper Aircraft Corporation, DMCR 1-1

10-12-58

Routine Maintenance performed

I CERTIFY THAT THIS Aircraft
HAS BEEN INSPECTED IN ACCORDANCE
WITH A 100 hr INSPECTION AND WAS
DETERMINED TO BE IN AIRWORTHY CONDITION.

J. Lee *QRP 1273676*

NOTICE:--Making false entries in this book is a violation of the Civil Aeronautics Act of 1938, punishable by Civil Penalty.

AIRCRAFT LOG

REMARKS

SIGNATURE

Dec. 15, 1958 - all A.D. notes checked for compliance
~~cleaned & greased spark plugs, checked~~ Remained and
 lubricated landing gear bolts, replaced worn bolts -
 inspected all controls, cables & pulleys - filled hydr.
 system - insp wheels & brakes,

I CERTIFY THAT THIS Aircraft
 HAS BEEN INSPECTED IN ACCORDANCE
 WITH A 100 hr INSPECTION AND WAS
 DETERMINED TO BE IN AIRWORTHY CONDITION.

J. Lee ACP 1273676

[illegible]

Place of Last Airplane Overhaul

Date of Last Overhaul

NOTICE:—Making false entries in this book is a violation of the Civil Aeronautics Act of 1938, punishable by Civil Penalty.

AIRCRAFT LOG

REMARKS	SIGNATURE
2-26-59 Inspect all controls, pulleys & cables - Removed all insp. covers and inspect interior of wings and fuselage - replaced all main landing gear bolts. Tightened and inspected all electrical fittings, replaced master fuse -	
I CERTIFY THAT THIS <u>Aircraft</u> HAS BEEN INSPECTED IN ACCORDANCE WITH <u>A/00 hr</u> INSPECTION AND WAS DETERMINED TO BE IN AIRWORTHY CONDITION.	
<u>J. Lee</u> ACP 1273676	

NOTICE:—Making false entries in this book is a violation of the Civil Aeronautics Act of 1938, punishable by Civil Penalties.

[illegible]

Place of Last Airplane Overhaul .

Date of Last Overhaul

NOTICE:—Making false entries in this book is a violation of the Civil Aeronautics Act of 1938, punishable by Civil Penalty.

AIRCRAFT LOG

REMARKS

SIGNATURE

3-18-59 A/D 58-16-1 Major lighter fuse circuit / not apply to this ^{series}
 all Routine Maintenance performed - ~~Cleaned & gapped spark plugs~~ -
 cleaned aircraft, inspected all controls, pulleys & cables - inspected
 wheel & Landing gear, filled hyd system, filled batteries.
 Removed fairings and inspected all part of aircraft internally.
 No A/D notes apply to this aircraft thru 59-5
 I certify this aircraft has been inspected in accordance
 to a periodic inspection and was determined to be
 airworthy - 2350 form issued March 18, 1959
 J. Lee Aep 1273676

NOTICE:—Making false entries in this book is a violation of the Civil Aeronautics Act of 1938, punishable by Civil Penalty.

AIRCRAFT LOG

REMARKS

SIGNATURE

Aug. 10, 1959

8-10-59 replaced left L. gear bolt, left shock cords,
cleaner & greased spark plugs, changed oil, inspected all
bolts & clamps, exhaust pipes - Inspect all cables, clamps,
controls, fairings.
A/D ~~and~~ 8-10-59 Gas tank caps drilled C/A.
~~A/D 8-10-59~~

I CERTIFY THAT THIS Aircraft
HAS BEEN INSPECTED IN ACCORDANCE
WITH A 100 hr INSPECTION AND WAS
DETERMINED TO BE IN AIRWORTHY CONDITION.

J. Lee ACP 1273676

[illegible]

Place of Last Airplane Overhaul

Date of Last Overhaul

Date of Last Overhaul

NOTICE:—Making false entries in this book is a violation of the Civil Aeronautics Act of 1938, punishable by Civil Penalty.

AIRCRAFT LOG

REMARKS

SIGNATURE

10-13-59 Routine Maint. performed, inspect landing gear bolts & shock cords, lubricated all controls, pulleys. charged battery, serviced brakes and nose gear with hyd. fluid.

I CERTIFY THAT THIS aircraft
HAS BEEN INSPECTED IN ACCORDANCE
WITH A 100 hr INSPECTION AND WAS
DETERMINED TO BE IN AIRWORTHY CONDITION.

J. Lee Dep 1273676

NOTICE:—Making false entries in this book is a violation of the Civil Aeronautics Act of 1938, punishable by Civil Penalty.

Date		Time In Air		Passengers Carried	NATURE OF FLIGHT
Year	Mo. Day	Hrs.	Min.		
1960					
1	30				
2	22	739	2	Tech	insp. all controls, cables, pulleys, lubricated all hinges. jacked airplane, checked landing gear, jacked airframe, cords, filled nose strut, checked airspeed pitot tube, checked fabric on fuselage. per A.D. 59-16-3 inspected prop for nicks. AD 60-1-7 c/wot 735 hrs. See back page for AD compliance See next page
Total Forward					

Place of Last Airplane Overhaul

Date of Last Overhaul

NOTICE:—Making false entries in this book is a violation of the Civil Aeronautics Act of 1938, punishable by Civil Penalty.

AIRCRAFT LOG

REMARKS

SIGNATURE

1-30-60 A.D. 60-1-7 C/W at this time, cleaned
tail brace wires, and ~~was~~ inspected for stone nicks & flaws
polished wires ~~was~~

J. Lee AEP 1273676

2-22-60 I certify this aircraft has been inspected
in accordance with a periodic insp. and
was determined airworthy. 2350 form used

J. Lee AEP 1273676 A.I.

NC

NATURE OF FLIGHT

Date		Time in Air Hrs. Min.		Passengers Carried	NATURE OF FLIGHT
Year Mo.	Day				
2-22	739	12	Tach	reads.	
7	15-60	816	34	Tach reading	—
Total Forward					

Place of Last Airplane Overhaul

Date of Last Overhaul

NOTICE:—Making false entries in this book is a violation of the Civil Aeronautics Act of 1938, punishable by Civil Penalty.

AIRCRAFT LOG

REMARKS	SIGNATURE
3-22-60	
3-27-60, AD 60-5-3 C/W at this time, installed pipe service bit 754-273, seat belt extension.	
	J. Lee AEP 1273676
7-13-60 AD 60-10-8 C/W at this time, fuel selector valve detent checked and inspected for proper operation.	
	J. Lee AEP 1273676

NOTICE:—Making false entries in this book is a violation of the Civil Aeronautics Act of 1938, punishable by Civil Penalty.

AIRCRAFT LOG

REMARKS

SIGNATURE

8-11-60 A/D 6-1-7 C/W checked tail brace
 wires for nicks - A/D 6-11-8 removed Sensenich prop
 and inspected for cracks as per A/D. All A/Ds previously
 C/W - inspected all wing & fuselage parts -
 59-16-3 C/W - inspect fabric at windshield edge

This aircraft has been inspected in accordance to
 a 100 hr inspection and was determined to be
 airworthy -

J. Lee ACP 1273676

[illegible]

Place of Last Airplane Overhaul

Date of Last Overhaul

Date of Last Overhaul

NOTICE:—Making false entries in this book is a violation of the Civil Aeronautics Act of 1938, punishable by Civil Penalty.

AIRCRAFT LOG

REMARKS

SIGNATURE

Curley's Aero Repair
HOWELL AIRPORT

3/30/61 Annual insp.. See Piper insp. form for details of insp.. Patch hole in wing fabric. Check & paint tail wires (A.D.60-1-7) Fuel valve checked (A.D.60-10-8). Windsheild fabric attachment checked (A.D.59-16-3). Fuel caps checked (A.D.59-10-8). Repaired nose gear mud guard attachment. Replaced seals in nose strut. Replaced engine mount. Repaired broken trim ~~ind.~~wire.
Tach-

I certify that this Aircraft has been inspected
in accordance with a Periodic
Inspection and was determined to be in an
airworthy condition.

P. D. Locke 1.A.

16404 Kedzie Ave. Harvey, Ill.

NOTICE:—Making false entries in this book is a violation of the Civil Aeronautics Act of 1938, punishable by Civil Penalty.

AIRCRAFT LOG

REMARKS

SIGNATURE

OCT 13, 1960 TACH READING 1042:21

THE FOLLOWING MAINTENANCE IN CONJUNCTION WITH
THE PERIODIC INSPECTION - ALL CONTROLS INSPECTED -
INSPECTION PLATES & FERRULES REMOVED - AIRCRAFT
INSPECTED & LUBRICATED INTERNALLY ALL PULLEYS HINGE
PINS - BRAKE CONTROL SYSTEM NR NOTES LISTED
AS FOLLOWS

51-19-2	NR	SER#	58-10-2	938 TINA OUTPORTS
51-23-3	NR	SER#	58-16-1	N/A SER#
51-27-3	NR	SER#	59-10-8	CAS CAP WORKED PROPERLY
53-24-4	NR	SER#	59-16-3	BY INSPECTION THIS DATE
55-7-2	NR	SER#	59-26-6	N/A BY SER#
558-4	NR	SER#	60-1-7	WIRES STAYED & PRINED THIS DATE
55-22-3	NR	TYPE CROSSED LIST	60-5-3	BRECKET PORT INSTALLED CHECKED BY MEASURING
57-17-2	BRECKET INSIDE OPERY			
57-22-1	INSPECTED THIS DATE			

NOTICE:—Making false entries in this book is a violation of the Civil Aeronautics Act of 1938, punishable by Civil Penalty.

AIRCRAFT LOG

REMARKS

SIGNATURE

A D NOTES (CONTINUED)

10-10-8 CHECKED THIS DATE DETAIL OF WORK WITH THIS DATE

61-6-6 BY INSPECTION THIS DATE FABRIC SECURE

61-16-5 NO BY S.A.R.H.

INTERIOR INSPECTED LINES SECURED UNDER POWER -

N. J. Kucki AP 1331219

I CERTIFY THAT THIS AIRCRAFT WAS INSPECTED IN
ACCORDANCE WITH A PERIODIC INSPECTION AND
WAS DETERMINED TO BE IN AN AIRWORTHY CONDITION
Warrant A. Wolf #1175441

AIRCRAFT LOG

REMARKS	SIGNATURE
AUG 22, 1962 INSTALLED STUBBEN MC CANNES TOW HITCH SER 337 THIS DATE	Norman A. Wagoner 1175441
SEPT 22, 1962 FAIRINGS REMOVED INSPECTION PLATES PULLED CONTROLS LUBRICATED & INSPECTED WHEELS CHECKED: HOLDS IN FABRIC PATCHED - CABLES CHECKED & LUBRICATED - SECURED LOOSE LINKS AD NOTES CHECKED TO 62-20-1 AS LISTED ON AP PREVIOUS PERIODIC COMPLETED 100 HR INSPECTION	N. J. Tucker 11330219
SEPT 22 TOTAL TIME 1139:16 I CERTIFY THAT THIS AIRCRAFT WAS INSPECTED IN ACCORDANCE WITH A PERIODIC INSPECTION AND WAS DETERMINED TO BE IN AN AIRWORTHY CONDITION	Norman A. Wagoner 1175441

AIRCRAFT LOG

	SIGNATURE
TACH READS 118000	
JULY 11, 1963 RECALIBRATED AT PHARADOCK	
WITH NEW PIPER PART FROM PIPER FACTORY	
AUG 31, 1963 ³ Left rear door removed	Norman A. Wolf 1502383
AUG 31, 1963 AIRCRAFT RECALIBRATED AS PER AIRCRAFT	
SPECS LISTED UNDER REMOVAL OF REAR DOOR.	
SUPPLEMENT TO OPERATIONS LIMITATIONS MADE	
OUT. SUPPLEMENT ADD LIMITS PLACED IN FULL	
VIEW OF PILOT AND HEAD OF OPERATIONS LIMITATIONS	
SUPPLEMENT FOR USE WHEN AIRCRAFT IS USED	
WHEN FLYING WITHOUT REAR DOOR. AIRCRAFT	
COMPLIES WITH SPECS LISTED IN AIRCRAFT SPECS.	
	Norman A. Wolf 1175441

AIRCRAFT LOG

REMARKS	SIGNATURE
1237.47	
OCT 26, 1963 TACH ROPS COMPLETE AIRCRAFT RECOVERY - FUSelage RECOVERED WITH ROYALTY IN ACCORDANCE WITH MOWM 200. WINES TRANSACTION L.C. AIRBORNE AND ROPS IN ACCORDANCE WITH 18-30-7(b)(5)(i). NOSE DOOR FINISHED WITH BUTYRATE COLOR - AIRCRAFT ASSEMBLED USING ALL NEW BOLTS. NEW TIRE INSTALLED ON RT SIDE - I CERTIFY THAT THIS AIRCRAFT WAS INSPECTED IN ACCORDANCE WITH A <u>CIVILIAN</u> INSPECTION AND WAS DETERMINED TO BE IN AN AIRWORTHY CONDITION Wanner A Wall #1175441	

AIRCRAFT LOG

REMARKS	SIGNATURE
Nov 17 1964 Periodic Insp: Rec tach 1294.9 Opened all inspection plates on wings, tail, & cabin fuselage; Cleaned oil & inspected all controls & control mechanisms; Serviced battery; Installed "O" ring in Parking brake; Installed new brake diaphragm in master cyl; Repaired Pitot tube; Repaired trim tab wire indicator; Drilled drain holes in wings & ailerons; Painted tail flying wires; Installed screws in gas tank; Painted left fuselage bad spot; Comply A D 64-5-4 on a/c strut (new type bearing & dust cover); Installed 2 door clips; Vacuumed cabin; Dressed prop & painted; Clean battery box; Tighten antennae; Work gas tanks; 2 new inspection plates; Serviced wheels; Packed bearings;	(over)

NOTICE:—Making false entries in this book is a violation of the Civil Aeronautics Act of 1938, punishable by Civil Penalty.

Date		Time in Air		Passengers Carried	NATURE OF FLIGHT
Year Mo.	Day	Hrs.	Min.		
					Run continued;
					Repaired nose gear mud flap; Stop Drilled
					crack in cowling; 3 small patches top left
					elevator; Logbook note 67-24-5 See back of
					book for listing compliance; I certify that I
					have inspected this aircraft in accordance
					with a periodic inspection + determined air-
					worthy;
					For name a. E. E. E. E.
					Insps Auth. 1140961
Total Forward					

Place of Last Airplane Overhaul

Date of Last Overhaul

NOTICE:—Making false entries in this book is a violation of the Civil Aeronautics Act of 1938, punishable by Civil Penalty.

AIRCRAFT LOG

REMARKS

SIGNATURE

9-9-66 Annual Inspection Rec tach 1295.7
 Opened all inspection plates + fairings
 thruout aircraft. Cleaned fuel & inspected
 all controls + control mechanisms thruout;
 Sanded + painted tail flying wires; installed
 cabin speaker; Painted nose gear + gear
 mud guards; Painted patrol can gear +
 left side of fuselage; installed new trim
 tab cable; Serviced nose gear wheel
 bearings + Shimmy dampener; installed
 new master cyl Diaphragm; Overhauled
 both main gear wheel cylinders; installed
 new fuel boost gasket; Repacked main
 wheel bearings; Last AD 66-21-1 others
 listed in back of book; New Battery

NOTICE:--Making false entries in this book is a violation of the Civil Aeronautics Act of 1938, punishable by Civil Penalty.

AIRCRAFT LOG

REMARKS

SIGNATURE

7/3/69 TACH. 1300 Hrs. replaced rudder elevator hinge pins - spliced both lower longerons. aft three feet replaced fabric on bottom where rotted out. patched fuselage where necessary replaced both rudder cables and all four aileron cables. top covered both wings and covered right aileron with grade A fabric greased wheel bearing. replaced battery rebuilt right wheel cylinder. Aircraft fabric painted with butyrate dope all metal painted with enamel. Patona white & Tennessee red.

I certify that this aircraft ~~entire~~ has been inspected in accordance with annual inspection and was determined to be in airworthy condition.

Total Time 1300 hrs Date 7-3-69

IA 1390760 of Capt. [Signature]

NOTICE:—Making false entries in this book is a violation of the Civil Aeronautics Act of 1938, punishable by Civil Penalty.

AIRCRAFT LOG TACH 1302.89

REMARKS

SIGNATURE

AUGUST 13, 1970, AIRCRAFT TOTAL
TIME 1302.89. ALL FAIRINGS AND
INSPECTION COVERS REMOVED.
ALL CONTROL SYSTEMS INSPECTED
AND LUBRICATED. ALL CABLES INSPE-
CTED. FABRIC TESTS AIRWORTHY.
ALL WHEEL BRGS. REPACKED. SER-
VICED NOSE GEAR OLEO AND BRAKE
SYSTEMS. I CERTIFY THAT THIS AIRCRAFT
HAS BEEN INSPECTED IN ACCORDANCE
WITH AN ANNUAL INSPECTION AND
WAS DETERMINED TO BE IN AIRWORTHY
CONDITION. Nicholas J. Kuch TA1331219

REMARKS

SIGNATURE

SEPT. 1, 1971. AIRCRAFT TOTAL
TIME 1340.12. ALL FAIRINGS AND
INSPECTION COVERS REMOVED,
FABRIC TESTS AIRWORTHY, ALL
CABLES INSPECTED, CONTROL
SYSTEMS INSPECTED AND LUBRICATED,
ALL WHEEL BRGS REPACKED. SERVICED
NOSE GEAR OLEO. AND BRAKE SYSTEM.

.....1340.12..... TOTAL TIME

I CERTIFY THAT THIS AIRCRAFT HAS BEEN
INSPECTED IN ACCORDANCE WITH AN ANNUAL
INSPECTION AND WAS DETERMINED TO BE IN
AIRWORTHY CONDITION.

Nicholas J. Kurba IA 1331219

M. J. Kuchi

AIRCRAFT LOG

TACH. 1353.19

NOV. 1, 1972

REMARKS

SIGNATURE

~~NOV. 1, 1972~~ AIRCRAFT TOTAL
TIME 1353.19. ALL PAIRINGS AND
INSPECTIONS REMOVED. ALL CONTROLS
SYSTEMS INSPECTED & LUBRICATED.
CABLES INSPECTED. ALL HINGE POINTS
LUBRICATED. FABRIC TESTS AIRWORTHY.
WHEEL BRGS. REPACKED. AIR FRAME
100 HR + ANNUAL INSPECTION. REPAINTED
FUSELAGE. INSTALLED STRIP OVER WINDSHIELD.
REPLACED RUSTY SCREENS.

.....1353.19..... TOTAL TIME

I CERTIFY THAT THIS AIRCRAFT HAS BEEN
INSPECTED IN ACCORDANCE WITH AN ANNUAL
INSPECTION AND WAS DETERMINED TO BE IN
AIRWORTHY CONDITION.

M. J. Kuchi IAH 1331219

NOTICE:—Making false entries in this book is a violation of the Civil Aeronautics Act of 1938, punishable by Civil Penalty.

AIRCRAFT LOG

REMARKS	SIGNATURE
<i>Work time 1352/34 1/7/73</i> <i>adjust clearance outer edge</i> <i>of right cylinder, top binding</i> <i>clearance satisfactory C. E. Kubin</i> <i>A.P. 2204767</i>	

NOTICE:—Making false entries in this book is a violation of the Civil Aeronautics Act of 1938, punishable by Civil Penalty.

AIRCRAFT LOG

REMARKS

SIGNATURE

toch 1375 1/20/74 - Repair of fuel line - Retime Wags - Replace
interconnected tension springs - Repair of fuselage tubing see 337 This
date, Recover horizontal stabilizer see 337 - Install Whelen Stroke Kit - C/w AD
73-9-6 - install placard, C/w AD 60-1-7 Tail Brakes, C/w AD 61-6-6 windshield
fabric installed but no further work required, installed new Battery, Rebuilt Gen
all routine service items performed per paper check sheet
C/w AD 60-10-8 by sign find ok. - C/w 67-24-2 - installed placard

I certify this AD has been inspected
in accordance with a 100 hr
inspection and was determined to be in
airworthy condition. 1/20/74

John Campbell A+P 1174653

CARDINAL AIRCRAFT SERVICE

CAMPBELL AIRPORT

GRAYSLAKE, ILLINOIS 60030

PH. 312-546-5150

I certify this AIRCRAFT has been inspected
in accordance with a ANNUAL
inspection and was determined to be in
airworthy condition. 1/20/74

2 RPA IA 1922500

CARDINAL AIRCRAFT SERVICE

CAMPBELL AIRPORT

GRAYSLAKE, ILLINOIS 60030

PH. 312-546-5150

NOTICE:—Making false entries in this book is a violation of the Civil Aeronautics Act of 1938, punishable by Civil Penalty.

AIRCRAFT LOG

REMARKS

SIGNATURE

12-13-37

ANNUAL INSPECTION. TALK READS - 1382:00 HRS.

THE FUSELAGE & DOORS WAS REPLACED. BOTH WINGS
AILERONS FLAPS FUSELAGE & RUDDER WAS RECOVERED
WITH CELCONITE. LANDING GEARS WAS RECOVERED WITH
GRADE-A-FRABRIC. ALL THIS NEW COVER WAS SPRAYED
WITH H. C. A. B. COLOR DOPE. ALL STEEL TUBING & PARTS
WAS CLEAN & PAINTED WITH ZINC-CHROMATE PAINT. ALL
NEW CONTROL CABLES, AILERONS FLAPS RUDDER & ELEVATORS
INSTALL THROUGH OUT. NEW CARPETS HEADLINER
WINDSHIELD & GLASSES INSTALL. NEW E. L. T. RADIO
INSTALL. ALL NEW FUEL LINES HOSES. NEW
BOLTS in Wing Fittings, Landing GEARS &
Wing STRUCTS INSTALL.

(OVER)

Date		Time in Air		Passengers Carried	NATURE OF FLIGHT
Year Mo.	Day	Hrs.	Min.		
					SEE FORM 337 FOR THE REPAIRS.
					A-D 60-01-07 TAIL BRACE WIRES C/W.
					A-D 74-17-04 FABRIC REINFORCEMENT. C/W.
					A-D 77-03-08 STEEL Wing STRUTS - C/W.
					A-D 77-09-09 FUEL TANK FILTER CAPS C/W N/A.
					A-D 59-10-08 GAS TANK CAP VENT. C/W.
					A-D 58-10-02 Wing LIFT STRUTS FORK 618 HRS. LEFT
					I certify that this <u>AIRCRAFT</u> has been inspected in accordance with a <u>ANNUAL</u> inspection as required by FAR - 43 and has been found airworthy.
					Inspector's signature <u>[Signature]</u>
					Inspection Authorization No. <u>235597</u>
					Total time in service <u>1382:00</u>
					Hours last 12 months <u>NONE</u>
					Date of inspection <u>12-13-77</u>
Total Forward					

Place of Last Airplane Overhaul

Date of Last Overhaul

NOTICE:—Making false entries in this book is a violation of the Civil Aeronautics Act of 1938, punishable by Civil Penalty.

AIRCRAFT LOG

REMARKS

SIGNATURE

3-8-78 NEW TACK INSTALL OLD TACK
READ 1382160 HR.

W. M. M. Darnell
A-E 235597

6-28-78 MODEL NO XPDR AT 50A
THIS TRANSPONDER HAS BEEN TESTED AND
FOUND TO COMPLY WITH FAR 91.177 +
PART 43 APPENDIX AND HAS BEEN FOUND
AIRWORTHY FOR RETURN TO SERVICE
TECH - Donald Lee Reed HC No 2258956

REED-REED AVIONICS, INC.

(Coffeyville Airport)

P. O. BOX 386

COFFEYVILLE, KS 67357

(316) 251-0780

THE AIRCRAFT AND/OR COMPONENTS
WAS REPAIRED AND INSPECTED IN ACCORDANCE
WITH CURRENT FEDERAL AVIATION REGULATIONS
AND FOUND AIRWORTHY FOR RETURN TO SERVICE

INSP. *Donald Lee Reed HC 2258956*

REPAIR STATION # 322-35

NOTICE:—Making false entries in this book is a violation of the Civil Aeronautics Act of 1938, punishable by Civil Penalty.

Date		Time in Air Hrs. Min.	Passengers Carried	NATURE OF FLIGHT
Year Mo.	Day			
DEC	13	1978		Annual inspection 337 form completed for Transponder installation new WAB list completed New EW 1132.2 CG 9.93. USEFUL LOAD 867.80 77-03-08 OWS in 1977 four (4) years remaining. 78-10-03 full cap Not Apply to this cap part number DEC 13 1978 Date _____ Tach 47:00 ELT BATT Due JAN 79 I certify that this <u>Aircraft</u> has been inspected in accordance with <u>Annual</u> inspection and was determined to be airworthy. Mechanic: <u>Stan R. Sheld</u> A & P 2154321 AF Total Forward <u>TT = 1382.6 + TACH</u>

Supervisor
Donall J. Keef
A/C 225956
4-17-79

Place of Last Airplane Overhaul Total time: 1429.6

Date of Last Overhaul

NOTICE:—Making false entries in this book is a violation of the Civil Aeronautics Act of 1938, punishable by Civil Penalty.

AIRCRAFT LOG

REMARKS

SIGNATURE

4-12-79

INSTALLED NARCO COMM 120 & ENTERED INTO
 AIRCRAFT RECORDS WEIGHT & BALANCE SUPPLEMENT
 DATED THIS DATE: 4-12-79

RICE-REED AVIONICS, INC.

Coffeyville Airport

P. O. BOX 386

COFFEYVILLE, KS 67357

[316] 251-0780

REPAIR STATION # 322-35

REPLACE ELT BATTERY BY:

AUG 4 0 1980

THE AIRCRAFT AND/OR COMPONENT IDENTIFIED
 WAS REPAIRED AND INSPECTED IN ACCORDANCE
 WITH CURRENT FEDERAL AVIATION REGULATIONS
 AND FOUND AIRWORTHY FOR RETURN TO SERVICE

INSP. Donald Lee Keef #225895C

TECH. Donald Lee Keef #225895C

Date Year Mo. Day	Time in Air Hrs. Min.	Passengers Carried	NATURE OF FLIGHT
12-28	TALK READS 131:80 HRS.		
	ALL CABLES & FLIGHT CONTROLS CHECK & LUBRICATED. NAV. LIGHTS REPAIRED ON R. Wing. BATTERY BOX CLEAN & ALL ELEC. SYSTEMS CHECK. BRAKES FILL WITH HYD. FLUID		
	ELT BATT. good TIL 8-28-80		
	ALL A-D NOTES LISTED IN BACK OF THIS BOOK A-D. 79-18-05 C/W ON ELT BATT.		
	MAC'S AIRCRAFT REPAIR Box 150B, Municipal Airport Pittsburg, Ks. 66762		
Total Forward			

I certify that this AIRCRAFT has been
inspected in accordance with ANNUAL
inspection as required by FAR - 43
and has been found airworthy.

Inspector's signature M. M. [Signature]
Inspection Authorization No. 235597
Total time in service 1514:40
Hours last 12 months 84:80
Date of inspection 12-28-79

Place of Last Airplane Overhaul

Date of Last Overhaul

NOTICE:—Making false entries in this book is a violation of the Civil Aeronautics Act of 1938, punishable by Civil Penalty.

AIRCRAFT LOG

REMARKS

SIGNATURE

12-28-79, Tach Reads - 131.80 hrs. Installed
new 12V Battery. Rebat R-35.
MAC'S AIRCRAFT REPAIR

Mark A. Cull
AOP 487622174

ALL A.D. NOTE'S LISTED
IN BACK OF BOOK

I certify that this A/C has been
inspected in accordance with Annex
inspection as required by FAR - 43
and has been found airworthy.

MAC'S AIRCRAFT REPAIR

Inspector's signature [Signature]
Inspection Authorization No. 235597
Total time in service 1520:54
Hours last 12 months ✓
Date of inspection 3-27-80

NOTICE:—Making false entries in this book is a violation of the Civil Aeronautics Act of 1938, punishable by Civil Penalties.

[illegible]

Place of Last Airplane Overhaul

Date of Last Overhaul

NOTICE:—Making false entries in this book is a violation of the Civil Aeronautics Act of 1938, punishable by Civil Penalty.

AIRCRAFT LOG

REMARKS

SIGNATURE

4-10-81 TALK READ'S 235:51 Hrs.
 ALL FLIGHT CONTROLS OK. & LUBRICATED WHEELS TIRES
 & BRAKES. NEW BAGG. INSTALL IN NOSE WHEEL. FABRIC
 TESTED GOOD. NEW WING STRUT FORKS INSTALL TO
 C/W AD 80-22-15. NEW E.I.T. BATT. INSTALL. BATTERY SER.
 & ALL ELEC. SYSTEM & LIGHTS OK. CLEAN ALL FUEL SCREENS.
 REPAIRED NOSE WHEEL FAIRING BRAKES.

I certify that this A/C has been
 Inspected in accordance with ANNUAL
 Inspection as required by FAR - 43
 and has been found airworthy.

Inspector's signature [Signature]
 Inspection Authorization No. 235597
 Total Time in service 1618:14
 Hours last 12 months 47:62
 Date of inspection 4-10-81

A-D 81-25-05 WING STRUT FORKS
 A-D 60-01-C' W TAIL BRAKES WIRES
 CLEAN & PAINTED.
 A-D'S LISTED IN BAC OF THIS BOOK
 E.I.T. BATT. GOOD TIL 5-82

NOTICE:—Making false entries in this book is a violation of the Civil Aeronautics Act of 1938, punishable by Civil Penalty.

LIST CAA-18-1 REPAIR AND ALTERATION FORMS HERE

- 60-1-7 c/w - tail hook wire insp #30-60
 59-16-3 fabric on windshield attach. c/w 739 hrs
 59-10-8 fuel tank caps drilled c/w - 8-10-59
 58-16-1 cigar lighter fuse ~~c/w~~ n/a to this serial
 58-10-2 wing lift strut fork²⁵⁰ n/a at this time 739 hrs
 58-10-2 wing lift strut fork²³⁷ n/a to this serial.
 57-22-1 fire prevention Remoib n/a to this serial.
~~57-17-2 seat belt attach²³ c/w. cancelled~~
 60-5-3 safety belt extensions installed as per Piper
 Service Bulletin #184 3-27-60 J.L.
 60-10-8 okay 1964
 61-6-6 recovery 1963 & 1964
 61-16-5 NOT APP. 1964
 63-23-2 NOT APP (300 HRS SMOH)
 64-4 DONE NOW (NEW BEARING BOOT 1964)
 64- NOT APP

LIST CAA-18-1 REPAIR AND ALTERATION FORMS HERE

72-21-3 CW PREV.

59-16-3 CW STRIP INSTALLED. 10/25/72

1/20/74 - c/w following A.D's

60-1-7 - Tail brace wires

60-10-8 - by inspection

61-6-6 - installed kit

67-24-2 - installed placed

72-21-3 - installed kit

73-9-6 - installed placed



in this bee

by Civil Po