

Aircraft Logbook Audit - N1490G



AIRCRAFT DESCRIPTION - NOTE AIRFRAME AND ENGINE TIMES ARE APPROXIMATE										
Year	Make	Model	Registration	Serial No.	AFTT	Engine	SMOH	MGTOW	Empty Wt	Useful Load
1962	Beechcraft	B33	N1490G	CD-476	5,646	IO-470-K	92538-7-K-R	3,000	1,930	1,070
Base Color	Trim 1	Trim 2	Rating	Int Material	Logbooks	Annual Due	TXP/Static Due	ADS-B	Oil Type	Spare
White	Red	Gold	9	Leather	Complete Original	07/31/26	07/31/27	I/O	Phillips XC 20W50	
LOGBOOK		DATE	AFTT	CATEGORY		DETAILS				
Airframe Log 1		Feb-62	0	Airframe - Inspection		Airworthiness Certificate issued				
		May-64	498	Airframe - Damage		LH OB leading edge wing skin replaced. All landing gear doors, retract rods replaced. Prop major OH'd. Replaced due to accidental gear retraction.				
		Mar-67	813	Instrument - Remove / Instal		Installed Mitchell Executive II autopilot IAW STC SA91SW.				
		Jun-67	867	Change - Hobbs / Tach		Installed FRM IO-470K engine and McCauley prop. Tach reset to 0.00.				
		Sep-69	1,096	Airframe - Mx / Repair		Installed Grimes strobe light kit				
		Oct-72	1,794	Airframe - Remove / Install		Installed External Power receptacle kit				
		May-78	3,278	Airframe - Mx / Repair		Installed RH elevator trim tab, painted and compensated and checked				
		Dec-81	3,768	Change - Hobbs / Tach		Removed, repaired and reinstalled LH Main fuel cell. Tach appears to have been updated to AFTT at this time.				
		Feb-84	3,951	Change - Hobbs / Tach		Installed rebuilt tach with correct time reading for the airframe				
		Mar-85	4,052	Airframe - Remove / Install		Aircraft approved for Auto Fuel STC IAW SA2049CE. See 337				
		Jun-89	4,245	Instrument - Remove / Instal		Removed Narco stack and installed King radio package				
		Oct-89	4,349	Airframe - Remove / Install		Installed Alcor Alternator kit IAW STC SA334SW. See 337				
Airframe Log 2		Aug-93	4,638	Airframe - Remove / Install		Installed Cee Bailey's One-piece windshield IAW STC SA358WE				
		Jul-94	4,693	Airframe - Mx / Repair		Removed elevators and checked balance. Repainted elevators at Aero Paint of El Cajon and re-balanced.				
		Jan-99	4,942	Engine - Overhaul		Reinstalled OH'd engine with new hoses, baffle seals and mounts. Replaced RH and LH fuel cells in new condition. Replaced motor brushes in MLG motor. Replaced brushes for flap motor. OH'd boost pump. Installed ADC oil filter IAW STC SA00402SE. Installed EDM 700 6C EGT/CHT IAW STC SA2586NM. Installed Prop Guard Tape IAW STC SP0058NY.				
		Sep-03	5,150	Airframe - Mx / Repair		Removed elevators and sent to Aero Surfaces for skin replacement.				
		Sep-03	5,150	Instrument - Remove / Instal		Installed new King radio package in place of previous, PM 3000 intercom, encoder, and GPS and annunciator. Installed RMD Wing Tips IAW STC SA5903NM and Shadin Microflo-L and transducer IAW STCs SA449GL and SE552GL				
		Feb-04	5,159	Instrument - Remove / Instal		Installed Century 2000 autopilot w/NSD 360 HIS IAW STC SA3489SW. See 337				
		Dec-03	5,159	Airframe - Paint / Interior		Complete chemical strip, chromate, prime and top coat with PPG DEP epoxy primer and PPG Delta custom colors.				
		Nov-05	5,218	Airframe - Mx / Repair		Replaced interior brake lines with new stratoflex hoses. Off'd turn coordinator. Replaced nose wheel assembly with new.				
		Jan-07	5,240	Airframe - Remove / Install		Installed Tanis TAS100 preheater system				
		Sep-07	5,299	Airframe - Mx / Repair		OH'd fuel boost pump				
		Oct-07	5,302	Airframe - Remove / Install		Installed new Ice Breakers on both MLG, low vacuum annunciator light, B&C standby generator system IAW STC SA00724WI, OH'd suction gauge, Alpha Aviation 3-point Torso Restraint system IAW SA01880CH. Installed MLG switch guard kit.				
		May-08	5,309	Airframe - Remove / Install		Replaced windshield IAW STC SA992NE. Replaced side windows IAW STC SA01078NY.				
		Aug-08	5,346	Airframe - Remove / Install		Installed PlanePower 70 amp alternator and regulator IAW STC SA10682SC. Installed S-TEC Yaw Damper IAW STC SA5102SW-D, Century Altitude Preselect. Installed K2U Flap Actuated Landing Gear system IAW STC				
		Apr-10	5,399	Airframe - Remove / Install		Installed dual yoke with copilot PTT switch.				
		Apr-11	5,415	Airframe - Remove / Install		Installed AirWolf air/oil separator IAW SA3523WE, Brackett air filter IAW STC SA71GL, Rosen sun visors IAW STC SA3598NM, and WAT strobe light on top of fuselage IAW SA615EA. See 337.				
		Aug-13	5,436	Airframe - Remove / Install		Installed Door Steward IAW STC SA1120SE				
		Nov-22	5,529	Instrument - Remove / Instal		Installed new instrument panel with the following new avionics in place of previous: Garmin G3X Touch, G5, GFC 500 autopilot with Yaw Damper, GTN 750Xi, GMA 35C, GNC355, GTX345R. Installed new CiES fuel senders at all cells. Installed Electroair Ignition/starter switch. Installed all new WAT wingtip and tail nav and strobe lights, top and bottom beacons, and landing light. Installed AeroLED wing taxi lights. Installed Artex ELT 345, GSB 15 USBs, and all new Klaxon CBs. Plumbed pitot static system to GSU25D and G5 AI.				

[illegible]