



06/02/2015

N201UW

Tach: 4022.16

Removed Skytech starter, installed new Skytech starter P/N 1-49-NL S/N FN-280694. Performed ops check no defects noted.


Monico Lopez AP3692583

**Elite Air Service 300 Airport dr
Coldwater MI 49036
517 278-6516**

07-07-2017<>N201UW<>SN:24-0390<>Engine Logbook<>Model:M20J<>Tach:4232.08

Performed the following maintenance items:

1. Drained engine oil and removed oil filter. Inspected oil filter for contamination, no defects noted. Installed 8 qts. Aeroshell W100 plus, (customer supplied), and new oil filter pn:AA48103-2. Ground run and leak checked ok.

I certify that this work has been inspected and determined to be in airworthy condition and approved for return to service with respect to the work performed. Pertinent details are on file this repair station under invoice number SHO-17-3425

Signature:



Ryan Grenhoff



Byerly Aviation, Inc. Greater Peoria Airport

Peoria, IL. 61607 Certificate # 9BYR810B

Feb 6, 2022 Hartzell Propeller

PC10 TC P920, Serial # HC-C24R-1Bfp

I certify that this propeller has been inspected in accordance with an annual inspection per FAR 43-13, Appendix D and determined it to be in airworthy condition

TSN 86.3

Garry S. Edson A&P 3469216 IA

A handwritten signature in black ink, appearing to read "Garry S. Edson", with a long horizontal flourish extending to the right.



Northwest Flyers



Schaumburg Regional Airport

Schaumburg Illinois

N201UW

Mooney M20J

SN# 24--390

Date 05-29-2013

Tach = 3863.2hrs

Inspected this aircraft for a one time flight from PWK to 06C per special flight permit dated 05-28-2013.

Complied with AD99-24-10 by inspection of standby vacuum.

Gene Scheuwimer

A&P1680919

07-07-2017<>N201UW<>SN:24-0390<>Airframe Logbook<>Model:M20J<>Tach:4232.08

Performed the following maintenance items:

- 1.RH fuel quantity indicator pegged full. Remove co-pilot seat and side interior, cleaned fuel probe wiring, and re-torqued ground screw. Operational tested RH fuel quantity, operational tested ok. Reinstalled interior.
- 2.Cleaned fuel selector shaft, and operational tested, ok.
- 3.Drained engine oil and removed oil filter. Inspected oil filter for contamination, no defects noted. Installed 8 qts. Aeroshell W100 plus, (customer supplied), and new oil filter pn:AA48103-2. Ground run and leak checked ok.

I certify that this work has been inspected and determined to be in airworthy condition and approved for return to service with respect to the work performed. Pertinent details are on file this repair station under invoice number SHO-17-3435.

Signature:  Ryan Grenhoff



Byerly Aviation, Inc. Greater Peoria Airport

Peoria, IL. 61607 Certificate # 9BYR810B

Mooney M20J N2010W Ser# 24-0390

06-06-2012

This date performed a very
minor foil dressing to the
tip of an blade of the
propeller

Edward A Van Reth A/P 3502862
