

A-36

E18SB

~~184458~~



**PROPELLER
SERVICE, INC.**

FAA -PS4R451M

**Burlington - Alamance Regional Airport
Burlington, NC 27215**

**Propeller Logbook
(336) 227-1467
1-800-334-6437**

LOW	
HIGH	

**DESCRIPTIONS OF ALL OPERATIONS
PERTAINING TO AIRWORTHINESS DIRECTIVES,
SERVICE BULLETINS, SERVICE LETTERS,
& MINOR ADJUSTMENTS**

DATE	TACH TIME	DESCRIPTION OF WORK	SIGNATURE
11-5-98	1636.15	CW 100 hr annual TMSR Reinstalled Prop on N1800V	
		MAINTENANCE RELEASE	
		THE <u>Annex</u> IDENTIFIED	
		ABOVE WAS REPAIRED AND INSPECTED IN ACCORDANCE WITH CURRENT INSTRUCTIONS CONTAINED IN ASHEVILLE JET, INC. REPAIR STATION INSPECTION PROCEDURES MANUAL, THE MAINTENANCE RULES OF THE FEDERAL AVIATION REGULATIONS UNDER WHICH THE OPERATOR IS CERTIFIED AND IS APPROVED FOR RETURN FOR SERVICE AS PER THOSE REQUIREMENTS.	
		*PERTINENT DETAILS OF THE REPAIR ARE ON FILE AT THIS REPAIR STATION UNDER WORK ORDER NO. <u>RS1887</u> DATE <u>11-5-98</u>	
		SIGNED <u>[Signature]</u>	
		FOR ASHEVILLE JET, INC. ASJR354B P.O. BOX 1209 FLETCHER, NC 28732	
		— END —	
		SEE ADLOG PROP LOG	

