

Textron (Beech) A36
**Airworthiness Directives
Compliance Report**

Date: 4/13/2026	Tail #: N1800V	Hours: AFTT:3788.7
Airframe: Textron (Beech) A36	S/N: E-1858	Hours: TSMOH: 2171.55
Front Engine: Continental IO-550-B	S/N: 297093-R	Hours: PTT: 3044.86, PTSMOH: 71.9
Front Propeller: McCauley 3A32C(4-- Series	S/N: 900697	

Airframe: Textron (Beech) A36							
AD# Eff Date Category	Subject	Date/Hours at Compliance	Method of Compliance	Notes	Rec	Date/Hours Next Due	Signature and Number
75-05-02 02/21/75 Airframe	Engine Oil	4/13/2026	Not applicable, air oil separator not installed on aircraft at this time.		Yes* (Terminating Action)		Joseph Rambosek AP 3761674 IA
93-24-03 01/21/94 Airframe	Rudder Forward Spar	4/13/2026 Tach: 3788.7	Complied with AD in accordance with MSB 2333, Revision 1, dated November 1991.		Yes* (Terminating Action)	4/13/2027 Or Tach:4288.7, Whichever occurs first	Joseph Rambosek AP 3761674 IA
95-04-03 04/07/95 Airframe	Wing Carry Through Frame Inspection	4/13/2026 Tach: 3788.7	Complied with AD in accordance with MSB 53-2360, REV. 1 Dated Issued: November, 1990 Revised: June, 2004 No cracking noted around huck bolts with dye penn.		Yes	Tach:4288.7, Whichever occurs first	Joseph Rambosek AP 3761674 IA
2001-08-08 06/07/01 Airframe	V-Band Exhaust Clamp		Not Applicable, aircraft not fitted with V-band clamps		Yes		Joseph Rambosek AP 3761674 IA
2007-08-08 05/25/07 Airframe	Landing Gear Uplock Rollers		Does not apply via Serial Number		Yes		Joseph Rambosek AP 3761674 IA
2023-09-09 07/17/23 Airframe	Exhaust Tailpipe V-Band Coupling		Equipment not on aircraft		Yes		Joseph Rambosek AP 3761674 IA

Front Engine: Continental IO-550-B							
AD# Eff Date Category	Subject	Date/Hours at Compliance	Method of Compliance	Notes	Rec	Date/Hours Next Due	Signature and Number
86-13-04 R3 02/24/88 Engine	Cylinder Assemblies Pressure Test	4/13/2026 Tach: 3788.7	Does not apply via Serial number		Yes* (Terminating Action)		Joseph Rambosek AP 3761674 IA
2009-19-07 10/07/09 Engine	EQ3 Cylinder Head Cracks	4/13/2026 Tach: 3788.7	Not applicable via serial number		Yes		Joseph Rambosek AP 3761674 IA
2014-05-29 04/25/14 Engine	SA52000-Axxx, SA55000-A1, and SA55000-A20P - (SAP) Cast Cylinder Assemblies	4/13/2026 Tach: 3788.7	Does not apply, continental cylinders installed at this time.		Yes		Joseph Rambosek AP 3761674 IA
2023-09-09 07/17/23 Engine	Exhaust Tailpipe V-Band Coupling	4/13/2026 Tach: 3788.7	Does not apply, equipment not installed at this time.		Yes		Joseph Rambosek AP 3761674 IA

Front Propeller: McCauley 3A32C(4-- Series							
AD# Eff Date Category	Subject	Date/Hours at Compliance	Method of Compliance	Notes	Rec	Date/Hours Next Due	Signature and Number
2007-08-04 05/17/07 Propeller	Manifold Limitation Placard And Life Limit Inspection	4/13/2026 Tach: 3788.7	Installed a new placard to the bottom left of the installed engine monitor due to analog tachometer being removed.		Yes	4/13/2027 OR Tach: 3888.7, Whichever occurs first	Joseph Rambosek AP 3761674 IA

Joseph B. Rambosek
AP 3761674 IA