

HARTZELL

# PROPELLER LOGBOOK

PROPELLER MODEL PHC-C3VF-1RF

PROPELLER S/N QG1414 B

LOGBOOK # \_\_\_\_\_

## PROPELLER MAINTENANCE RECORD

Position \_\_\_\_\_

PITCH RANGE

Propeller Model \_\_\_\_\_

High/Feather \_\_\_\_\_

Propeller S/N \_\_\_\_\_

Start Lock \_\_\_\_\_

Blade Design \_\_\_\_\_

Low \_\_\_\_\_

Blade S/N's

Reverse \_\_\_\_\_

No. 1 \_\_\_\_\_

No. 2 \_\_\_\_\_

No. 3 \_\_\_\_\_

No. 4 \_\_\_\_\_

No. 5 \_\_\_\_\_

No. 6 \_\_\_\_\_

Aircraft Manufacturer BEECH

Aircraft Model A-36

S/N \_\_\_\_\_

Registration N527R\$

Spinner Assembly Part No. \_\_\_\_\_

Date

PROP MODEL:  
PHC-C3YF-1RF  
PROP S/N: EE-4782B  
REG. NO: 527RS  
WORK ORDER:  
1441-10-2017



### Scanlon Aviation

451 Airport Road  
Novato, CA 94945  
Phone: 415-897-9787

DATE: 25 January, 2018  
A/C TSN: 1841.3  
PROP TT: 0  
HOBBS: 1841.3

### Prop Entries

(2) Installed Hartzell PHC-C3YF-1RF/F8068K s/n QG1414B per STC# SA02556CH-D. Installation made per Instructions INST\_012308FLD and Hartzell Drawing 102544 for De-Ice ring installation. Ice slip rind adjusted by dial indicator per drawing per Hartzell service instructions to .002" run-out (limit .005").

I certify this propellor has been inspected in accordance with an ANNUAL inspection and was determined to be in an airworthy condition.

DATE: 25 January, 2018

SIGNED:

Kenneth R Robbins, IA: 3129824

Work Order: 1441-10-2017

Printed by EBis 3 (datcomedia.com)

PROP MODEL:  
PHC-C3YF-1RF/F8068K  
PROP S/N: QG1414B  
REG. NO: 527RS  
WORK ORDER:  
1638-01-2019



### Scanlon Aviation

451 Airport Road  
Novato, CA 94945  
Phone: 415-897-9787

DATE: 08 February, 2019  
A/C TSN: 1932.6  
PROP TT: 91.3  
HOBBS: 1932.6

### Prop Entries

(3) Performed annual inspection of propeller per FAR 43 appendix D checklist. Greased hub per Hartzell Service Instructions.

I certify this propellor has been inspected in accordance with an ANNUAL inspection and was determined to be in an airworthy condition.

DATE: 08 February, 2019

SIGNED:

Kenneth R Robbins, IA: 3129824

Work Order: 1638-01-2019

Printed by EBis 3 (datcomedia.com)

PROP MODEL:  
PHC-C3YF-1RF/F8068K  
PROP S/N: QG1414B  
REG. NO: 527RS  
WORK ORDER:  
1830-01-2020



### Scanlon Aviation

451 Airport Road  
Novato, CA 94945  
Phone: 415-897-9787

DATE: 13 February, 2020  
A/C TSN: 2008.9  
PROP TT: 167.6  
HOBBS: 2008.9

#### Prop Entries

(3) Performed annual inspection of propeller per FAR 43 appendix D checklist. Greased hub per Hartzell Service Instructions.... (12)  
Propeller profiled free of nicks.

I certify this propeller has been inspected in accordance with an ANNUAL inspection and was determined to be in an airworthy condition.

DATE: 13 February, 2020

SIGNED:

John O'Connell, IA: 3564328

Work Order: 1830-01-2020

Printed by EBis 3 (datcomedia.com)

PROP MODEL:  
PHC-C3YF-1RF/F8068K  
PROP S/N: QG1414B  
REG. NO: 527RS  
WORK ORDER:  
2029-02-2021



### Scanlon Aviation

451 Airport Road  
Novato, CA 94945  
Phone: 415-897-9787

DATE: 01 March, 2021  
A/C TSN: 2075.1  
PROP TT: 233.8  
HOBBS: 2075.1

#### Prop Entries

(3) Performed annual inspection of propeller per FAR 43 appendix D checklist. Greased hub per Hartzell Service Instructions.

I certify this propeller has been inspected in accordance with an ANNUAL inspection and was determined to be in an airworthy condition.



DATE: 01 March, 2021

SIGNED:

John O'Connell, IA: 3564328

Work Order: 2029-02-2021

Printed by EBis 3 (datcomedia.com)

Date	Propeller TSN TSO	A/C Hrs	Description of all operations pertaining to Airworthiness Directives, Service Documents, Overhaul, Major or Minor Repair, and Inspections.
	PROP MODEL: PHC-C3YF-1RF/F8068K PROP S/N: QG1414B REG. NO: 527RS WORK ORDER: 2227-02-2022	<b>Scanlon Aviation</b> 451 Airport Road Novato, CA 94945 Phone: 415-897-9787	DATE: 31 March, 2022 A/C TSN: 2107.3 PROP TT: 266 HOBBS: 2107.3
	<b>Prop Entries</b> (3) Performed annual inspection of propeller per FAR 43 appendix D checklist. Greased hub per Hartzell Service Instructions. Airworthiness directives checked thru ATP Rev. 03/29/2022.		
	I certify this propellor has been inspected in accordance with an ANNUAL inspection and was determined to be in an airworthy condition.		
	DATE: 31 March, 2022	SIGNED:  John OConnell, IA: 3564328	Work Order: 2227-02-2022 Printed by EBis 3 (datcomedia.com)
	PROP MODEL: PHC-C3YF-1RF/F8068K PROP S/N: QG1414B REG. NO: 527RS WORK ORDER: 2473-03-2023	<b>Scanlon Aviation</b> 451 Airport Road Novato, CA 94945 Phone: 415-897-9787	DATE: 14 April, 2023 A/C TSN: 2140.2 PROP TT: 298.9 HOBBS: 2140.2
	<b>Prop Entries</b> (3) Performed annual inspection of propeller per FAR 43 appendix D checklist. Greased hub per Hartzell Service Instructions. Airworthiness directives checked thru ATP Rev. 04/14/2023		
	I certify this propellor has been inspected in accordance with an ANNUAL inspection and was determined to be in an airworthy condition.		
	DATE: 14 April, 2023	SIGNED:  John OConnell, IA: 3564328	Work Order: 2473-03-2023 Printed by EBis 3 (datcomedia.com)

2728-04-2024 (05-24-2024)

Page 1 / 1

MAKE: Raytheon Aircraft Co  
MODEL: A36  
S/N: E3222  
REG. NO: 527RS  
PROP MAKE: HARTZELL  
PROP MODEL: PHC-C3YF-  
1RF/F8068K  
PROP 1 SN: QG1414B



**Scanlon Aviation**  
451 Airport Road  
Novato, CA 94945

W/O #: 2728-04-2024  
DATE: 05-24-2024  
A/C TT: 2170.5  
A/C Tach:  
Landings:  
Prop TT: 329.2

### Propeller Entries

Performed annual inspection of propeller per FAR 43 appendix D checklist. Greased hub per Hartzell Service Instructions.  
Airworthiness directives checked thru ATP Rev. 5/24/2024...

I certify this aircraft has been inspected in accordance with an ANNUAL inspection and was determined to be in an airworthy condition.

DATE: 05-24-2024

SIGNED:

John OConnell  
IA: AP3564328IA

WORK ORDER: 2728-04-2024

Printed by EBIS (EBISCloud.com)

2891-11-2024 (06-06-2025)

Page 1 / 1

MAKE: Raytheon Aircraft Co  
MODEL: A36  
S/N: E3222  
REG. NO: 527RS  
PROP MAKE: HARTZELL  
PROP MODEL: PHC-C3YF-  
1RF/F8068K  
PROP 1 SN: QG1414B



**Scanlon Aviation**  
451 Airport Road  
Novato, CA 94945

W/O #: 2891-11-2024  
DATE: 06-06-2025  
Prop TSN: 362.2  
Prop TT: 362.2

### Prop Entries

Performed annual inspection of propeller per FAR 43 appendix D checklist. Greased hub per Hartzell Service Instructions.  
Airworthiness directives checked thru ATP Rev. 6/5/2025.

I certify this propeller has been inspected in accordance with an 100/ANNUAL inspection and was determined to be in an airworthy condition.

DATE: 06-06-2025

SIGNED:

John OConnell  
A&P: AP3564328IA

WORK ORDER: 2891-11-2024

Printed by EBIS (EBISCloud.com)

## **HARTZELL PROPELLER INC.**

One Propeller Place

Piqua, Ohio 45356-2634 U.S.A.

Telephone: 937.778.4200

Telex: 4332032

Fax: 937.778.4391